

Oil Field Environmental Incident Summary

Incident: 20180906210634 **Notice:** 9/6/2018 21:06 **Occurred:** 9/6/2018 09:22

Responsible Party: SCOUT ENERGY MANAGEMENT LLC

Well Operator: SCOUT ENERGY MANAGEMENT LLC

Well Name: HAMILL 4-27 SWD

Field Name: T. R.

Well File #: 8387

Facility ID #:

County: BILLINGS

Twp Rng Sec Qtr: 141 101 27 SW NW

Location Description:

Submitted By: Beki Sample

Received By:

Contact Info:
 Beki Sample
 4901 LBJ FREEWAY, STE 300
 DALLAS TX 75244

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 3 Mile

Nearest Water Well: 2 Mile

Type of Incident: Pipeline Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	75	Barrels	75	Barrels	75	barrels
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/10/2018

Written Report Recd: 4/25/2019

Risk Evaluation:

N/A

Areal Extent:

N/A

Potential Env. Impacts:

There will be no environmental impacts as the spill was contained within the dike

Action Taken/Planned:

A vac truck was dispatched and recovered the spilled production water. It was taken to the 41X-27H and put into storage tanks to be disposed of.

Wastes Disposal Location:

Contaminated soil will be hauled to Indian Hills disposal.

Other Agencies Involved:

Updates

Date: 9/7/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Schiermeister, Robin

Notes:

Release, due to a pipeline leak, remained on the well pad. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update