

Oil Field Environmental Incident Summary

Incident: 20180912085222 **Notice:** 9/12/2018 08:52 **Occurred:** 9/12/2018 01:30

Responsible Party: SECURE ENERGY SERVICES USA, LLC

Well Operator: SECURE ENERGY SERVICES USA, LLC

Well Name: 13 MILE SWD 1

Field Name: TYRONE

Well File #: 90159

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 156 101 12

Location Description:

Submitted By: Josh Rolston

Received By:

Contact Info: Josh Mosbrucker
5807 West Front St
WILLISTON ND 58801

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 20 Feet

Nearest Water Well: 200 Feet

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1	Barrels	1	Barrels		
Brine	9	Barrels	9	Barrels		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

none

Action Taken/Planned:

called in hydr vac to suck up all standing water and used loader to remove all contaminated gravel.

Wastes Disposal Location:

onsite waste pad.

Other Agencies Involved:

Updates

Date: 9/12/2018 **Status:** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: O'Gorman, Brian

Notes:

Release, due to a valve/piping connection leak was contained on the well site, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update