Oil Field Environmental Incident Summary

Responsible Party: Pelican Gathering Systems LLC

Well Operator: SLAWSON EXPLORATION COMPANY, INC.

Well Name: PAYARA 3-21H
Field Name: VAN HOOK
Well File #: 25546

Facility ID #:

County: MOUNTRAIL
Twp Rng Sec Qtr: 152 91 21

Location Description:

Submitted By: Raymond Gorka

Received By:

Contact Info: Dave Gerbig

1675 BROADWAY STE 1600

DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use:CultivatedNear. Occupied Bldg:3340 FeetNearest Water Well:3340 FeetType of Incident:Pump Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 62 Barrels 18 Barrels

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

none.

Areal Extent:

Inside and outside of berm.

Potential Env. Impacts:

none as clean up was immediate and swift. No penetration/contact with groundwater.

Action Taken/Planned:

Pelican will improve the berm the pump sits in to minimize any future incidents such as this from occurring again.

Wastes Disposal Location:

Secure Energy services.

Other Agencies Involved:

Updates

Date: 9/14/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Release, due to a pump leak was contained to the well site, according to the report. NDIC retains

oversight.

Updated Volumes and Contaminant None at the time of this update