

Oil Field Environmental Incident Summary

Incident: 20180918125128 **Notice:** 9/18/2018 12:51 **Occurred:** 9/17/2018 18:10

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: PARSHALL SECTION 16 CENTRAL FACILITY
Field Name: PARSHALL
Well File #:
Facility ID #: 228315-01
County: MOUNTRAIL
Twp Rng Sec Qtr: 152 90 16 SE SW
Location Description:
Submitted By: Brenda Vaness
Received By:
Contact Info: Brenda Vaness
600 17TH ST., STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Tank Leak
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	15	Barrels	14	Barrels	15	barrels
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 9/25/2018
Written Report Recd: 10/22/2018

Risk Evaluation:

N/A

Areal Extent:

Potential Env. Impacts:

N/A

Action Taken/Planned:

The tank was isolated and emptied to stop the spill. A hydrovac removed contaminated material, and flushed the area with fresh water and removed it for disposal. The damaged tank will be removed, and further cleanup will be done underneath the tank.

Wastes Disposal Location:

Secure, Stanley, ND

Other Agencies Involved:

MHA & TAT

Updates

Date: 9/18/2018 ***Status:*** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: Stockdill, Scott

Notes:

Release occurred within the Fort Berthold Reservation. Forward to BIA/Tribal authorities.

Updated Volumes and Contaminant None at the time of this update