

# Oil Field Environmental Incident Summary

**Incident:** 20180920114937      **Notice:** 9/20/2018      11:49      **Occurred:** 9/20/2018      03:30

**Responsible Party:** WHITE OWL ENERGY SERVICES (US) INC.

**Well Operator:** WHITE OWL ENERGY SERVICES (US) INC.

**Well Name:** WO NEWTOWN 1

**Field Name:** ANTELOPE

**Well File #:** 90170

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 152   95   13

**Location Description:**

**Submitted By:** Mike Pinnell

**Received By:**

**Contact Info:** Todd Johnston  
P.O. BOX 1953  
DICKINSON ND 58602

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 1 Mile

**Nearest Water Well:**

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	25	Barrels			25	barrels
Brine	350	Barrels			320	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 10/18/2018

**Written Report Recd:** 11/9/2018

**Risk Evaluation:**

No immediate risk, spill is contained on well site.

**Areal Extent:**

**Potential Env. Impacts:**

No environmental impacts as spill is contained on well site.

**Action Taken/Planned:**

A vac truck was called in right away to suck up the fluid. Republic services was called in to remove all of the contaminated dirt.

**Wastes Disposal Location:**

Republic Services in Alexander, ND

**Other Agencies Involved:**

## ***Updates***

---

***Date:*** 9/20/2018      ***Status:*** Reviewed - Assigned to Other Agency

***No Further Action:*** ☒

***Author:*** Stockdill, Scott

***Notes:***

According to the incident summary, this release remained on location. NDIC retains oversight.

***Updated Volumes and Contaminant***   None at the time of this update