

# *Oil Field Environmental Incident Summary*

**Incident:** 20181016080554      **Notice:** 10/16/2018 08:05      **Occurred:** 10/12/2018 1400

**Responsible Party:** CasedHole Solutions  
**Well Operator:** SLAWSON EXPLORATION COMPANY, INC.  
**Well Name:** TORPEDO FEDERAL 7H  
**Field Name:** BIG BEND  
**Well File #:** 31275  
**Facility ID #:**  
**County:** MOUNTRAIL  
**Twp Rng Sec Qtr:** 152 91 30 SE SE  
**Location Description:** Well site and onto the residence of Mr. & Mrs. Devin Dorval  
**Submitted By:** Raymond Gorka  
**Received By:**

**Contact Info:** Adrian Eby  
 4946 HWY 85  
 Williston ND 58801

**Affected Medium:** Topsoil  
**General Land Use:** Other - Described Above  
**Near. Occupied Bldg:** 815 Feet  
**Nearest Water Well:** 815 Feet  
**Type of Incident:** Equipment Failure  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	5	Gallons				

**Oth Rel. Contaminant:** Lubricating Oil, Royal Wireline Lubricating Oil. Non-hazardous with OSHA 20 CFR 1910.1200. Biodegradation >80%

**Date Inspected:**  
**Clean Up Concluded:**  
**Written Report Recd:**  
**Risk Evaluation:**

none

**Areal Extent:**  
 Approximately an area of 15,000 yards was impacted.

**Potential Env. Impacts:**  
 none

**Action Taken/Planned:**  
 Lubricator was re-adjusted.

**Wastes Disposal Location:**  
 Secure Energy Services.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 10/16/2018    **Status:** Reviewed - Assigned to Other Agency    **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this release occurred within the MHA Nation boundaries.  
Forward to BIA/tribal authorities.

**Updated Volumes and Contaminant**    None at the time of this update