

Oil Field Environmental Incident Summary

Incident: 20181031110930 **Notice:** 10/31/2018 11:09 **Occurred:** 10/30/2018 02:00

Responsible Party: HENRY HILL OIL SERVICES, LLC

Well Operator: HENRY HILL OIL SERVICES, LLC

Well Name: NELSON 1 SWD

Field Name: LONE TREE LAKE

Well File #: 90404

Facility ID #:

County: WILLIAMS

Twp Rng Sec Qtr: 157 99 9

Location Description:

Submitted By: Matt Azure

Received By:

Contact Info: Matt Azure
120 26TH STREET EAST
SUITE 200
WILLISTON ND 58801

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg: 1 Mile

Nearest Water Well: 1 Mile

Type of Incident: Tank Overflow

Release Contained: Yes - Within Dike

Reported to NRC: Yes

	<i>Spilled</i>	<i>Units</i>	<i>Recovered</i>	<i>Units</i>	<i>Followup</i>	<i>Units</i>
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine	50	Barrels	50	Barrels		
--------------	----	---------	----	---------	--	--

Other

Oth Rel. Contaminant: salt water and oil

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

NA stayed in lined containment

Areal Extent:

Potential Env. Impacts:

NA

Action Taken/Planned:

all brine was sucked up and put back unto system.

Wastes Disposal Location:

everything stayed on site

Other Agencies Involved:

NDIC

Updates

Date: 10/31/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Crowdus, Kory

Notes:

Release remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update