

# *Oil Field Environmental Incident Summary*

**Incident:** 20181031151512      **Notice:** 10/31/2018 15:15      **Occurred:** 10/31/2018 11:00

**Responsible Party:** WHITING OIL AND GAS CORPORATION

**Well Operator:** WHITING OIL AND GAS CORPORATION

**Well Name:** PERIOT 44-20HU

**Field Name:** DOLLAR JOE

**Well File #:** 27666

**Facility ID #:**

**County:** WILLIAMS

**Twp Rng Sec Qtr:** 156 96 20 SE SE

**Location Description:**

**Submitted By:** Brian Wurm

**Received By:**

**Contact Info:** Brian Wurm  
1700 BROADWAY STE 2300  
DENVER CO 80290

**Affected Medium:** Topsoil

**General Land Use:** Pasture

**Near. Occupied Bldg:** 0.2 Mile

**Nearest Water Well:** 0.2 Mile

**Type of Incident:** Treater Popoff

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3	Gallons	3	Gallons	3	gallons

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 11/12/2018

**Written Report Recd:** 11/19/2018

**Risk Evaluation:**

Minimal risk anticipated. The release has been stopped and cleanup is in progress.

**Areal Extent:**

Approximately 10 feet by 20 feet to the east off location

**Potential Env. Impacts:**

Minimal environmental impacts anticipated. The release has been stopped and cleanup is in progress.

**Action Taken/Planned:**

A vac truck was brought in to pick up impacted material on site and offsite impacts will be addressed to the landowners requirements.

**Wastes Disposal Location:**

Gibson Disposal

**Other Agencies Involved:**

## Updates

---

**Date:** 10/31/2018      **Status:** Reviewed - Follow-up Required

**No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release impacted areas off location. Follow-up is required.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 11/2/2018      **Status:** Inspection

**No Further Action:**

**Author:** Schmitt, Bryan

**Notes:**

Time: 11:15 CT

Temp: 34 F

Treater failure that impacted an area of approximately 25x40 feet of pasture land to the East of the well pad. All vegetation has been removed and no impacts were observed on the soil. Follow-up to monitor vegetation regrowth.

**Updated Volumes and Contaminant**    None at the time of this update

---

**Date:** 3/27/2019      **Status:** Inspection

**No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

Arrived on location 6:27 3/27/2019.

No sign of remaining contaminants or contamination.

No follow-up is necessary.

**Updated Volumes and Contaminant**    None at the time of this update