

Oil Field Environmental Incident Summary

Incident: 20181102171813 **Notice:** 11/2/2018 17:18 **Occurred:** 11/1/2018 20:20

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: HIDATSA NORTH 14-23HUL

Field Name: REUNION BAY

Well File #: 33645

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 150 93 11

Location Description: Active well location

Submitted By: Deborah Watson

Received By:

Contact Info: Deborah Watson
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons			0	gallons

Brine

Other

Oth Rel. Contaminant: crude oil

Date Inspected:

Clean Up Concluded: 11/5/2018

Written Report Recd: 11/16/2018

Risk Evaluation:

There are no immediate risks associated with this incident.

Areal Extent:

12' X 5'-very light mist of oil onto vegetation beyond edge of constructed well pad.

Potential Env. Impacts:

There are no potential environmental impacts associated with this incident. Third party to delineate off site impact-off site soil not impacted by oil mist.

Action Taken/Planned:

Crew contained situation with TIW valve-crew will make sure that they are pumping additional fluids down the annular while pulling so they cover displacement.

Wastes Disposal Location:

TBD-likely PDI landfill

Other Agencies Involved:

MHA, BIA

Updates

Date: 11/5/2018 ***Status:*** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, the release was not contained to the well pad. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update