

Oil Field Environmental Incident Summary

Incident: 20181103140529 **Notice:** 11/3/2018 14:05 **Occurred:** 11/2/2018 18:01

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: RAPTOR 13-24HZ

Field Name: REUNION BAY

Well File #: 34139

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 150 92 18

Location Description:

Submitted By: Deborah Watson

Received By:

Contact Info: Deborah Watson
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels			0	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 11/5/2018

Written Report Recd: 11/16/2018

Risk Evaluation:

No immediate risk, majority of impact on location. Impact off location is light mist to vegetation in the area-no standing oil.

Areal Extent:

Oil mist impacted area on pad is 250 ft x 50 ft, off pad in neighboring pasture is 100 ft x 50 ft

Potential Env. Impacts:

There are no potential environmental impacts associated with this incident. Oil mist-no standing fluids. Third party to delineate off site impact-off site soil not believed to be impacted by oil mist.

Action Taken/Planned:

Switched to a different flowback vessel that was functioning correctly-took vessel that was not functioning correctly out of service.

Wastes Disposal Location:

PDI treatment facility, PDI landfill

Other Agencies Involved:

MHA, BIA, BLM, TAT Environmental

Updates

Date: 11/5/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release of 10 barrels of oil was not contained to the well pad. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update