Oil Field Environmental Incident Summary

		- 44/0/0040	47.00	44/0/040	10.00	
Incident: 2018110617		e: 11/6/2018		Occurred: 11/6/2018	10:09	
Responsible Party:	OASIS PETROLEUM NORTH AMERICA LLC					
Well Operator:	OASIS PETROLEUM NORTH AMERICA LLC					
Well Name:	BWL SWD 5201 11-3					
Field Name:	BAKER					
Well File #:	28634					
Facility ID #:						
County:	MCKENZIE					
Twp Rng Sec Qtr:	153 100 19					
Location Description:						
Submitted By:	Dustin Anderson					
Received By:						
Contact Info:	Dustin Anderson					
	6205 16th Ave W					
	Williston ND 58801					
Affected Medium		Will/Facility Soil				
Affected Medium:	•					
General Land Use:	Well/Facility Site					
Near. Occupied Bldg:	1 Mile					
Nearest Water Well:	1 Mile					
Type of Incident:	Valve/Piping Connection Leak					
Release Contained:	Yes - On Facility Site					
Reported to NRC:	No					
Spilled	Units	Recovered	Units	Followup	Units	
Oil						
Brine 10	Barrels	5	Barrels			
Other						
Oth Rel. Contaminant: produced water						
Date Inspected:						
Clean Up Concluded:						
Written Report Recd:						
Risk Evaluation:						
Low - contained on well pad						
Areal Extent:						
7,046 sq ft						
Potential Env. Impacts:						
Low - all released fluid is contained to the well pad						
Action Taken/Planned:						
Unknown at this time						
Wastes Disposal Location:						
Indian Hills Special Waste disposal						
Other Agencies Involved:						
Other Agencies invol						

Updates

 Date:
 11/7/2018
 Status:
 Reviewed - Assigned to Other Agency
 No Further Action:
 ✓

 Author:
 DeVries, Taylor

Notes:

According to the incident report, the release was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update