## Oil Field Environmental Incident Summary

Incident: 20181115160429 Notice: 11/15/2018 16:04 Occurred: 11/15/2018 10:30

Responsible Party: Cobra Oil and Gas Corp
Well Operator: ENDURO OPERATING, LLC

Well Name: LITTLE TANK 19-21

Field Name: LITTLE TANK

**Well File #:** 7167

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 148 101 19

Location Description:

Submitted By: Paulette Vedvik

Received By:

Contact Info: Dra Parr

PO Box 8206

Wichita Falls TX 76307

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Tank Overflow Release Contained: Yes - Within Dike

Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnits30Barrels30Barrels30barrels

Brine Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 11/15/2018 Written Report Recd: 12/27/2018

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

none

Action Taken/Planned:

Scraped up and hauled to R 360

Wastes Disposal Location:

R 360

Other Agencies Involved:

## **Updates**

Date: 11/15/2018 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: O'Gorman, Brian

Notes:

Release, due to a tank overflow, was contained within the diking, according to the report. NDIC

retains oversight.

Updated Volumes and Contaminant None at the time of this update