Oil Field Environmental Incident Summary

Incident: 20181119101953)53 N o	otice: 11/19	9/2018	10:19	Occurre	d: 11/18/20 ²	18 5	Sunday	
Responsible Party:		daryl Andersen								
Well Operator:		DOUBLE AA OIL, L.L.C.								
Well Name:		Adams CTB								
Field Name:		WILEY								
Well File #:										
Facility ID #:		206365-01								
County:		BOTTINEAU								
Twp Rng Sec Qtr:		161 82 27 NE SW								
Location Description:		flare pit behind treater which is also within the dike								
Submitted By:		Daryl Andersen								
Received	-	,								
Contact Info:		daryl andersen								
		PO BOX 402								
		WESTHOPE ND 58793-0402								
Affected	Affected Medium:		Westhope ND 58793-0402 Well/Facility Soil							
General Land Use:		Well/Facility Ste								
Near. Occupied Bldg:		2 Mile								
Nearest Water Well: Type of Incident:		Treater Popoff								
Release Contained:		Yes - Within Dike								
Reported to NRC:		Unknown								
Spilled		Units Recovered Units Followup Units								
Oil	2	Barrels		2	Barrels					
Brine	8	Barrels		8	Barrels					
Other										
Oth Rel. Contaminant: none										
Date Ins	pected:									
-	Concluded:									
Written Report Recd:										
Risk Evaluation:										
none										
Areal Extent:										
Potential Env. Impacts:										
none										
Action Taken/Planned:										
cleaned up. tearing treater apart to find problem										
Wastes Disposal Location:										
in tanks										
Other Agencies Involved:										

Updates

Date: 11/19/2018 Status: Reviewed - Assigned to Other Agency No Further Action: 🗸

Author: O'Gorman, Brian

Notes:

Release, due to a treater popoff, was contained within the diking, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update