

Oil Field Environmental Incident Summary

Incident: 20181119164456 **Notice:** 11/19/2018 16:44 **Occurred:** 11/18/2018 18:30

Responsible Party: XTO ENERGY INC.
Well Operator: XTO ENERGY INC.
Well Name: DEER PASS 20-3
Field Name: INDIAN HILL
Well File #: 11470
Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 153 101 20
Location Description:
Submitted By: Gregory Hoppe
Received By:
Contact Info: Kaylan Dirkx
 110 WEST 7TH STREET
 FORT WORTH TX 76102

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Tank Overflow
Release Contained: Yes - Within Dike
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	3	Barrels	3	Barrels	3	barrels

Brine
Other

Oth Rel. Contaminant: Crude oil from storage tank.

Date Inspected:
Clean Up Concluded: 11/28/2018
Written Report Recd: 1/3/2019

Risk Evaluation:
 Minimal - spill contained on site and being cleaned up.

Areal Extent:
 All liquid was contained within the secondary containment.

Potential Env. Impacts:
 Minimal potential impact to surrounding area.

Action Taken/Planned:
 Work activities should be done earlier in the day to ensure enough light to observe well facility. As well as not producing into a tank that is that full.

Wastes Disposal Location:
 IHD

Other Agencies Involved:
 N/A

Updates

Date: 11/20/2018 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Release, due to a tank overflow, was contained within the diking, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update