Oil Field Environmental Incident Summary

Incident: 20190109114919 Notice: 1/9/2019 11:49 Occurred: 1/9/2019 04:30

Responsible Party: COMPLETE ENERGY SERVICES, INC Well Operator: COMPLETE ENERGY SERVICES, INC

Well Name: DAVID 1-12 SWD PLEASANT VALLEY Field Name:

Well File #: 90246

Facility ID #:

County: **WILLIAMS**

Twp Rng Sec Qtr: 156 95 12 SE SE

The spill occurred on the David 1-12 SWD Location Location Description:

Submitted By: Jason Henderson

Received By:

Contact Info: Jason Henderson

4727 GAILLARDIA PKWY, STE 250

OKLAHOMA CITY OK 73142

Affected Medium: Well/Facility Soil General Land Use: Well/Facility Site

Near. Occupied Bldg: 2 Mile

Nearest Water Well:

Type of Incident: Tank Overflow

Release Contained: Yes - On Facility Site

Reported to NRC: No

Spilled Units Recovered **Units** 40 Barrels 40 Barrels **Brine** 262 **Barrels** 262 Barrels

Other

Oil

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: Written Report Recd:

Risk Evaluation:

No risk hazards

Areal Extent:

300 BBLs were contained, 2 BBLs estimated outside containment 50' x 4' area

Potential Env. Impacts:

No environmental impacts as we immediately started cleaning the sight and removing the stained soil

Action Taken/Planned:

Contaminated soils are being scraped up and disposed of in a landfill that accepts oilfield RCRA exempt waste.

Wastes Disposal Location:

300 BBLs were contained inside concrete containment and will be pumped back into the facility tanks. 2 BBLs that sprayed over containment will be removed with hydrovac and placed back into the facility tanks. We will dispose of any solids collected in the hydrovac as an approved oilfield RCRA exempt landfill that has not been determined at this time.

Other Agencies Involved:

Followup

Units

NDIC field inspector was notified and will be inspecting the site this afternoon.

Updates

Date: 1/9/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 1/11/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

1/10/2019 at 11:12, on location. Met with site personnel and observed personnel cleaning up site. All material spilled appears to have stayed on site, no evidence fluid that sprayed outside of concrete secondary containment around storage tanks escaped facility's tertiary perimeter containment. No further follow-up required, NDIC retains jurisdiction.

Updated Volumes and Contaminant None at the time of this update

Date: 1/28/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Received disposal receipt from responsible party and added it to incident folder.

Updated Volumes and Contaminant None at the time of this update