

Oil Field Environmental Incident Summary

Incident: 20190109170034 **Notice:** 1/9/2019 17:00 **Occurred:** 1/9/2019 10:15

Responsible Party: PETRO-HUNT DAKOTA, LLC

Well Operator: PETRO-HUNT DAKOTA, LLC

Well Name: CAPER 5-22-15H

Field Name: BOXCAR BUTTE

Well File #: 25846

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 149 102 22

Location Description:

Submitted By: Shawn Reisenauer

Received By:

Contact Info: Shawn Reisenauer
390 119th Ave. SW
Killdeer ND 58640

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Pipeline Leak

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	15	Barrels	15	Barrels	15	barrels
Oth Rel. Contaminant:	Emulsion					

Date Inspected:

Clean Up Concluded: 1/15/2019

Written Report Recd: 3/13/2019

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

Vac truck was dispatched to site to begin sucking free fluids, all other contaminated soils will be scraped up and hauled to disposal and replaced with clean materials. That portion of flowing will be replaced.

Wastes Disposal Location:

Indian Hills

Other Agencies Involved:

Updates

Date: 1/9/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update