

Oil Field Environmental Incident Summary

Incident: 20190110170947 **Notice:** 1/10/2019 17:09 **Occurred:** 1/10/2019 11:42

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: AUSTIN 7-23H
Field Name: PARSHALL
Well File #: 16972
Facility ID #:
County: MOUNTRAIL
Twp Rng Sec Qtr: 154 90 23
Location Description: Offsite 10'x20' area NE corner
Submitted By: Danielle Dupay
Received By:
Contact Info: Danielle Dupay
600 17TH ST., STE 1000N
DENVER CO 80202

Affected Medium: Topsoil
General Land Use: Cultivated
Near. Occupied Bldg:
Nearest Water Well:
Type of Incident: Stuffing Box Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Gallons	10	Gallons	10	gallons

Brine
Other

Oth Rel. Contaminant:
Date Inspected:

Clean Up Concluded: 1/10/2019
Written Report Recd: 9/20/2019

Risk Evaluation:
N/A

Areal Extent:
Oil mist on top of snow on a 10"x20" area offsite NE corner of location

Potential Env. Impacts:
N/A

Action Taken/Planned:
Offsite misted snow was brought onto location and piled up with the onsite affected rock and snow. A hydrovac was used to suck up the affected snow and rock and taken to disposal.

Wastes Disposal Location:
Stanley Secure Facility

Other Agencies Involved:

Updates

Date: 1/10/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 1/14/2019 **Status:** Inspection

No Further Action:

Author: Stockdill, Scott

Notes:

Arrived on location 4:38 1/14/2019.

No sign of remaining contaminants or contamination. Field to NW of well pad has been scraped up. It is hard to discern if the snow piled in the NE corner is from the impacted area or not.

Follow-up with company on disposal.

No onsite follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update