

# Oil Field Environmental Incident Summary

**Incident:** 20190115161734      **Notice:** 1/15/2019    16:17    **Occurred:** 1/14/2019    18:03

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** VAN HOOK 3-25H

**Field Name:** VAN HOOK

**Well File #:** 17463

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 152 91 25

**Location Description:**

**Submitted By:** Danielle Dupay

**Received By:**

**Contact Info:**  
Danielle Dupay  
600 17TH ST., STE 1000N  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Tank Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	240	Barrels	240	Barrels	240	barrels

**Oth Rel. Contaminant:** Treater Manufactured Salt Water

**Date Inspected:**

**Clean Up Concluded:** 1/15/2019

**Written Report Recd:** 2/22/2019

**Risk Evaluation:**

N/A

**Areal Extent:**

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A vac truck was used to suck up liquids off the ground. The snow, slush and dirt was removed with dirt moving equipment and will be removed and disposed of.

**Wastes Disposal Location:**

Liquids were disposed of at EOG Shell Creek SWD, Solids will be disposed of at Clean Harbors and Wisco

**Other Agencies Involved:**

## Updates

---

**Date:** 1/15/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Crowdus, Kory

**Notes:**

Release remained on location, according to the report. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update