

Oil Field Environmental Incident Summary

Incident: 20190115165636 **Notice:** 1/15/2019 16:56 **Occurred:** 1/15/2019 06:00

Responsible Party: EOG RESOURCES, INC.
Well Operator: EOG RESOURCES, INC.
Well Name: PARSHALL SECTION 30 NENW CENTRAL FACILITY
Field Name: PARSHALL
Well File #:
Facility ID #: 217522-01
County: MOUNTRAIL
Twp Rng Sec Qtr: 152 90 30 NE NW
Location Description:
Submitted By: Danielle Dupay
Received By:
Contact Info: Danielle Dupay

600 17TH ST., STE 1000N
 DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Equipment Failure
Release Contained: Yes - On Facility Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	60	Barrels	60	Barrels	60	barrels
Other						

Oth Rel. Contaminant:
Date Inspected:

Clean Up Concluded: 1/15/2019
Written Report Recd: 2/22/2019

Risk Evaluation:
 N/A

Areal Extent:
Potential Env. Impacts:
 N/A

Action Taken/Planned:
 Vac trucks were called to remove liquids from ground and hydrovacs were used to removed snow/slush and contaminated material.

Wastes Disposal Location:
 Liquids were put back into the facility tanks and solids were taken to Stanley Secure

Other Agencies Involved:

Updates

Date: 1/16/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.

Updated Volumes and Contaminant None at the time of this update