

Oil Field Environmental Incident Summary

Incident: 20190116112213 **Notice:** 1/16/2019 11:22 **Occurred:** 1/15/2019 16:40

Responsible Party: Arrow Water, LLC

Well Operator: ARROW WATER, LLC

Well Name:

Field Name:

Well File #:

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 148 92 5 NE NW

Location Description: Pipeline right of way bell hole.

Submitted By: Mitch Lagerstrom

Received By:

Contact Info:
Jill McCaskill
10702 Highway 73
Keene ND 58847

Affected Medium: Topsoil

General Land Use: Other - Described Above

Near. Occupied Bldg: 2005 Feet

Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - On Pipeline ROW

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	250	Barrels	215	Barrels		
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

No immediate health hazards

Areal Extent:

Potential Env. Impacts:

No impact or potential impact to ground water.

Action Taken/Planned:

Remove all impacted soils

Wastes Disposal Location:

Other Agencies Involved:

MHA Energy, TAT Environmental

Updates

Date: 1/16/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Location is within MHA Nation. Report forwarded to MHA Environmental, BIA and EPA.

Updated Volumes and Contaminant None at the time of this update