

# *Oil Field Environmental Incident Summary*

**Incident:** 20190117152534      **Notice:** 1/17/2019    15:25    **Occurred:** 1/16/2019    14:30

**Responsible Party:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Operator:** BURLINGTON RESOURCES OIL & GAS COMPANY LP

**Well Name:** GLACIERSON 1-4 UTFH-ULW

**Field Name:** CLEAR CREEK

**Well File #:** 31396

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 151 96 9 SW SW

**Location Description:** Spill stayed on the well production pad.

**Submitted By:** Kelsy Waggaman

**Received By:**

**Contact Info:**  
Kelsy Waggaman  
600 N. DAIRY ASHFORD  
HOUSTON TX 77079

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>						
<b>Other</b>	10	Barrels				

**Oth Rel. Contaminant:** Mix of hot water and possible produced water.

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

None

**Areal Extent:**

**Potential Env. Impacts:**

Produced water released to snow and gravel on pad.

**Action Taken/Planned:**

Bowie pump was set to unload to empty vehicle into tank.

**Wastes Disposal Location:**

**Other Agencies Involved:**

## **Updates**

---

**Date:** 1/17/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** O'Gorman, Brian

**Notes:**

Release, due to a truck overflow, was contained to the site, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update