## Oil Field Environmental Incident Summary

**Occurred:** 2/18/2019 Incident: 20190218084214 Notice: 2/18/2019 08:42 05:00

Responsible Party: Petro-Hunt, LLC Well Operator: PETRO-HUNT, L.L.C.

Well Name: CLEAR CREEK 152-96-34B-5H

Field Name: **CLEAR CREEK** 

Well File #: 24534

Facility ID #:

County: **MCKENZIE** 

Twp Rng Sec Qtr: 152 96 34 NW NW

**Location Description:** 

Derek Enderud Submitted By:

Received By:

Contact Info: Derek Enderud

**PO BOX 935** 

BISMARCK ND 58502

Affected Medium: Well/Facility Soil **General Land Use:** Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other Release Contained: No Reported to NRC: No

> **Spilled Units** Recovered Units **Followup Units** 20 gallons

Oil 20 Gallons

**Brine** Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 2/19/2019 Written Report Recd: 3/13/2019

Risk Evaluation:

None

Areal Extent:

25' x 50' area on outside of the fence. Mist on top of snow.

Potential Env. Impacts:

None, mist is light and stayed on top of snow.

Action Taken/Planned:

Contaminated snow will be removed and hauled off.

Wastes Disposal Location:

Secure-Keene

Other Agencies Involved:

## **Updates**

Date: 2/19/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of oil was not contained to the well pad. Further follow-

up is needed.

**Updated Volumes and Contaminant** None at the time of this update

Date: 2/20/2019 Status: Inspection No Further Action: ✓

Author: O'Gorman, Brian

## Notes:

Arrived on location at 11:50. 5 degrees F, Calm winds, Foggy. Observed the site and took photos. There was an area south of the flare that had the snow removed and barb wire on the fence removed. It appeared that a majority of the impacted snow had been removed. Follow-up in spring/summer 2019 for proper vegetative growth in the area. Photos added to the incident folder.

**Updated Volumes and Contaminant** None at the time of this update

Date: 9/24/2019 Status: Inspection - No Action Required No Further Action: ✓

Author: Crowdus, Kory

## Notes:

On location 9/24/2019, at 2:18pm. Vegetation in area is green and growing and looks consistent throughout. No further follow up is required.

Updated Volumes and Contaminant None at the time of this update