Oil Field Environmental Incident Summary

Responsible Party: WHITING OIL AND GAS CORPORATION Well Operator: WHITING OIL AND GAS CORPORATION

Well Name: ROHDE 44 1H CTB

Field Name: SANISH

Well File #:

Facility ID #: 217895-01
County: MOUNTRAIL

Twp Rng Sec Qtr: 153 92 1 SE SE

Location Description: A misted formation of 60'x3' was hiccupped out of the flare from

depressurizing a treater totaling up to 5 gallons of crude released offsite to

the Northeast of the pad.

Submitted By: Shelby Lego

Received By:

Contact Info: Shelby Lego

1700 BROADWAY STE 2300

DENVER CO 80290

Affected Medium: Topsoil
General Land Use: Pasture
Near. Occupied Bldg: 1.7 Mile
Nearest Water Well: 1.7 Mile
Type of Incident: Treater Leak

Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 5 Gallons 5 Gallons

Brine Other

Oth Rel. Contaminant: Up to 5 gallons of oil misted offsite during treater depressurization allowing

unknown liquid in the flare line to mist off location.

Date Inspected:

Clean Up Concluded: Written Report Recd: Risk Evaluation:

No immediate health hazards.

Areal Extent:

60'x3' Mist formation

Potential Env. Impacts:

The mist was able to be skim-shoveled as it lay on top of the snow. No potential impacts.

Action Taken/Planned:

The top layer of snow was skimmed off allowing 100% of released oil to be removed.

Wastes Disposal Location:

Waste will be disposed of at an approved disposal site.

Other Agencies Involved:

Updates

Date: 2/19/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: DeVries, Taylor

Notes:

According to the incident report, the release of oil was not contained to the well pad. Location is within MHA Nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update