Oil Field Environmental Incident Summary

Responsible Party: MUREX PETROLEUM CORPORATION **Well Operator:** MUREX PETROLEUM CORPORATION

Well Name: DWIGHT LUDWIG 13-24H

Field Name: WRITING ROCK

Well File #: 26207

Facility ID #:

County: DIVIDE

Twp Rng Sec Qtr: 161 101 13 NE NW

Location Description:

Submitted By: William Jansky

Received By:

Contact Info: Shannon Holter

363 N. Sam Houston Pkwy. E.

Suite 200

HOUSTON TX 77060

Affected Medium: Topsoil
General Land Use: Pasture
Near. Occupied Bldg: 2000 Feet

Nearest Water Well:

Type of Incident: Stuffing Box Leak

Release Contained: No **Reported to NRC:** Yes

	Spilled	Units	Recovered	Units	Followup	Units
Oil	10	Barrels	9.5	Barrels	9.5	barrels
Brine	20	Barrels	20	Barrels	20	barrels

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 7/4/2019 Written Report Recd: 9/20/2019

Risk Evaluation:

Minimal

Areal Extent:

100'X250'

Potential Env. Impacts:

Minimal

Action Taken/Planned:

Well was shut in. A vacuum truck was called to recover ponded fluids. Frozen ground and snow cover limited fluids ground penetration and movement. Equipment was used to scrape up the fluids. Less than 10 gallons misted off site to the NE. The impacted areas were snow covered and were scraped up with no ground contamination.

Wastes Disposal Location:

A flat tank will be used to contain the impacted material until it melts and can be disposed of through the SWD pipeline.

Other Agencies Involved:

Updates

Date: 3/8/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Crowdus, Kory

Notes:

Release impacted areas off location. Follow-up is required.

Updated Volumes and Contaminant None at the time of this update

Date: 3/25/2019 Status: Inspection No Further Action: ✓

Author: Nieraeth, Shawna

Notes:

3/19/2019 - Visited well pad. Contamination scraped up and piled behind pump jack, near flare pit on the south side of the pad. According to report, it's supposed to be contained but it's on the ground and melting. Couldn't tell where it went off pad - area is melting and messy. Suggest vegetation check in the spring/summer.

Updated Volumes and Contaminant None at the time of this update

Date: 3/27/2019 Status: Inspection No Further Action: ✓

Author: Stockdill, Scott

Notes:

Arrived on location 1:35 3/27/2019.

No sign of impacts of off location. There is standing water on site with oil present. Contact Murex to ensure water doesn't migrate off of site.

More follow-up by phone.

Updated Volumes and Contaminant None at the time of this update

Date: 7/26/2019 Status: Inspection No Further Action: ✓

Author: Biemiller, Richard

Notes:

Arrived on site 07/23/2019 at 255PM. It was Sunny and in the 80's. Looked over perimeter of pad, especially Northeast area. No discoloration of vegetation or odor detected. Vegetation looks good. OK to close.

Updated Volumes and Contaminant None at the time of this update