

Oil Field Environmental Incident Summary

Incident: 20190310221108 **Notice:** 3/10/2019 22:11 **Occurred:** 3/10/2019 09:00

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: GUDMURI 1-1-26TFH-ULW

Field Name: ELIDAH

Well File #: 30973

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 151 97 26

Location Description:

Submitted By: Kelsy Waggaman

Received By:

Contact Info: Kelsy Waggaman
925 North Eldridge Pkwy
HOUSTON TX 77079

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	1.1	Barrels				

Brine

Other

Oth Rel. Contaminant: None

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None.

Areal Extent:

40'X250'. Of this total area, a 30'X75' mist left location.

Potential Env. Impacts:

Oil mist on snow.

Action Taken/Planned:

THIS WELL WAS SHUTDOWN AT THE TIME THAT THE SPILL WAS DISCOVERED. It will remain down until the reason from the PRV release can be determined.

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 3/11/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Martin, Russell

Notes:

Release due to unspecified cause, was not contained on location, according to the report. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 3/29/2019 **Status:** Inspection

No Further Action:

Author: Schiermeister, Robin

Notes:

Arrived on site at 18:49 on 3-26-2019. The sun was starting to set; however, temperatures were still in the 50s. Walked around the perimeter of the well pad and saw no signs of contamination. No further follow-up is necessary at this time.

Updated Volumes and Contaminant None at the time of this update