Oil Field Environmental Incident Summary

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP
Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: NORMAN 11-4TFH ULW

Field Name: FANCY BUTTES

Well File #: 26962

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 150 96 4

Location Description:

Submitted By: Kelsy Waggaman

Received By:

Contact Info: Kelsy Waggaman

925 North Eldridge Pkwy HOUSTON TX 77079

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg: Nearest Water Well:

Type of Incident: Other Release Contained: No Reported to NRC: No

Spilled Units Recovered Units Followup Units

Oil 0.3 Barrels

Brine Other

Oth Rel. Contaminant: None

Date Inspected: Clean Up Concluded: Written Report Recd: Risk Evaluation:

None.

Areal Extent:

The spray area was 300'x 60'x .0012" with some spray off location.

Potential Env. Impacts:

Oil mist on snow.

Action Taken/Planned:

Work Order has been entered to clean up the spill.

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 3/11/2019 Status: Reviewed - Follow-up Required No Further Action: ✓

Author: Martin, Russell

Notes:

Release due to unspecified cause, was not contained on location, according to the report. Follow-up

is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 3/29/2019 Status: Inspection No Further Action: ✓

Author: Schiermeister, Robin

Notes:

Arrived on site at 9:33 on 3-27-2019. It was sunny with temperatures in the 40s. Walked along the perimeter of the well pad and saw no signs of contamination from the snow melt. No further follow-up is necessary at this time.

Updated Volumes and Contaminant None at the time of this update