Oil Field Environmental Incident Summary

Incident: 20190313123518 Notice: 3/13/2019 12:35 Occurred: 3/12/2019 18:00

Responsible Party:WPX ENERGY WILLISTON, LLCWell Operator:WPX ENERGY WILLISTON, LLCWell Name:LAWRENCE BULL 1-12H CTB

Field Name: SOUTH FORK

Well File #:

 Facility ID #:
 234649-01

 County:
 DUNN

Twp Rng Sec Qtr: 149 92 33 SW SW

Location Description: At the tank battery and behind the tank battery to the southeast.

Submitted By: Adam Ries

Received By:

Contact Info: Adam Ries

3500 One Williams Center- MD38

TULSA OK 74172

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg: 0.7 Mile
Nearest Water Well: 0.5 Mile
Type of Incident: Tank Overflow

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

SpilledUnitsRecoveredUnitsFollowupUnitsOil50Barrels50Barrels50barrels

Brine Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/16/2019
Written Report Recd: 9/6/2019

Risk Evaluation:

No immediate risks associated with this release.

Areal Extent:

2,000 square feet inside containment and 2,000 square feet outside containment.

Potential Env. Impacts:

Release impacted well/Facility soil and snow. No potential impacts to off-Facility lands.

Action Taken/Planned:

Fluids will be recovered with vacuum trucks. Impacted snow, ice, and soil from the release will be removed. Above-ground infrastructure will be washed.

Wastes Disposal Location:

E&P exempt, permitted SWD, full service terminal, and landfill.

Other Agencies Involved:

MHA, TAT, BIA, BLM

Updates

Date: 3/13/2019 Status: Reviewed - Assigned to Other Agency No Further Action: ✓

Author: Martin, Russell

Notes:

Release due to tank overflow, remained on location, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update