

Oil Field Environmental Incident Summary

Incident: 20190314080949 **Notice:** 3/14/2019 08:09 **Occurred:** 3/13/2019 08:22

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: PATTEN 5B-1-1

Field Name: LITTLE KNIFE

Well File #: 8588

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 144 97 5

Location Description:

Submitted By: Jesse Trotter

Received By:

Contact Info: Jesse Trotter
390 119th Ave. SW
Killdeer ND 58640

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Barrels	2	Barrels	3	barrels

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 3/13/2019

Written Report Recd: 9/6/2019

Risk Evaluation:

none

Areal Extent:

Potential Env. Impacts:

No expected impacts as everything was contained inside the dike.

Action Taken/Planned:

Isolated recycle line and pumper called a vac truck in to suck up any standing fluid, then washed contaminated soils.

Wastes Disposal Location:

Recycled into our own slop tanks

Other Agencies Involved:

Updates

Date: 3/14/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to valve/piping connection leak remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update