

# *Oil Field Environmental Incident Summary*

**Incident:** 20190314160533      **Notice:** 3/14/2019    16:05    **Occurred:** 3/13/2019    16:30

**Responsible Party:** EOG RESOURCES, INC.  
**Well Operator:** EOG RESOURCES, INC.  
**Well Name:** FERTILE 49-3024H  
**Field Name:** PARSHALL  
**Well File #:** 20691  
**Facility ID #:**  
**County:** MOUNTRAIL  
**Twp Rng Sec Qtr:** 151 90 30 SE SW  
**Location Description:** 10 gallon offsite mist on top of snow to the south.  
**Submitted By:** Danielle Dupay  
**Received By:**

**Contact Info:** Danielle Dupay  
 600 17TH ST., STE 1000N  
 DENVER CO 80202

**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**  
**Nearest Water Well:**

**Type of Incident:** Other

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	1	Barrels	1	Barrels		

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

N/A

**Areal Extent:**

10 gallons offsite to south in 10' x 50' area on top of the snow

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

The misted snow was brought back onto location and onsite misted snow has been piled up to be disposed. Phone calls have been made to the landowner and verbal contact has not been made at this time and will continue calling the owner until verbal contact is made.

**Wastes Disposal Location:**

TBD

**Other Agencies Involved:**

## **Updates**

---

**Date:** 3/14/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release due to unspecified cause, was not contained on location, according to the report. Location is within MHA Nation. Report forwarded to MHA Environmental, BIA, and EPA.

**Updated Volumes and Contaminant**    None at the time of this update