

Oil Field Environmental Incident Summary

Incident: 20190314160927 **Notice:** 3/14/2019 16:09 **Occurred:** 3/12/2019 14:00

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: BIG BEND 31-2H

Field Name: CAMEL BUTTE

Well File #: 17973

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 151 96 2

Location Description:

Submitted By: Kelsy Waggaman

Received By:

Contact Info: Kelsy Waggaman
925 North Eldridge Pkwy
HOUSTON TX 77079

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Other

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.4	Gallons				

Brine

Other

Oth Rel. Contaminant: None

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

The Fire scorched an area 10' X 10'X .0625 = 0.01 bbls

Potential Env. Impacts:

Charred facility soil inside of flare berm.

Action Taken/Planned:

Work order submitted for clean up

Wastes Disposal Location:

TBD

Other Agencies Involved:

Updates

Date: 3/14/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to unspecified cause (presumably a fire), remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update