

# Oil Field Environmental Incident Summary

**Incident:** 20190314160956      **Notice:** 3/14/2019      16:09      **Occurred:** 3/14/2019      09:30

**Responsible Party:** PETRO-HUNT, L.L.C.

**Well Operator:** PETRO-HUNT, L.L.C.

**Well Name:** USA 153-95-4B-9-5H

**Field Name:** CHARLSON

**Well File #:** 32532

**Facility ID #:**

**County:** MCKENZIE

**Twp Rng Sec Qtr:** 154 95 33

**Location Description:**

**Submitted By:** Jesse Trotter

**Received By:**

**Contact Info:** Jesse Trotter  
390 119th Ave. SW  
Killdeer ND 58640

**Affected Medium:** Topsoil

**General Land Use:** Pasture

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Fire

**Release Contained:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
--	----------------	--------------	------------------	--------------	-----------------	--------------

**Oil**

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 3/14/2019

**Written Report Recd:** 9/6/2019

**Risk Evaluation:**

none, the fire has been put out.

**Areal Extent:**

80'x180'

**Potential Env. Impacts:**

Vegetation was burned but expect no impacts since there was no fluid that was released.

**Action Taken/Planned:**

Ordered a liquid capturing vessel, so in the event of gas going through the high pressure flare it will collect any fluids that may cause the flare to increase in size. We are also trying to move the flare further into the pad and away from the hill side.

**Wastes Disposal Location:**

**Other Agencies Involved:**

U.S. Army Corpse of Engineers- Casey Beuchler

## **Updates**

---

**Date:** 3/14/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Martin, Russell

**Notes:**

Fire on location. Nothing released off location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update