

Oil Field Environmental Incident Summary

Incident: 20190317110723 **Notice:** 3/17/2019 11:07 **Occurred:** 3/15/2019 23:45

Responsible Party: BRUIN E&P OPERATING, LLC
Well Operator: BRUIN E&P OPERATING, LLC
Well Name: FORT BERTHOLD 152-94-11B-14-10H
Field Name: ANTELOPE
Well File #: 34963
Facility ID #:
County: MCKENZIE
Twp Rng Sec Qtr: 152 94 2 SW SE
Location Description:
Submitted By: Julia Traster
Received By:
Contact Info: Dusty Grosulak
 511 16TH ST., STE 200
 DENVER CO 80202

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 0.7 Mile
Nearest Water Well: 0.7 Mile
Type of Incident: Other
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	17.8	Barrels	17.8	Barrels		

Oth Rel. Contaminant: Biodegradable WG-35 Gel was spilled onto the soil/scoria on the well site.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

There were no personal injuries. There were no immediate health hazards.

Areal Extent:

120 square feet

Potential Env. Impacts:

Minimal. The cleaned up gel is biodegradable.

Action Taken/Planned:

Supervisor spoke to operators about paying more attention to the equipment they are running/operating. A hydrovac was used to pick up all the spilled gel.

Wastes Disposal Location:

Little Knife Disposal

Other Agencies Involved:

Updates

Date: 3/18/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

According to the report, WG-35 gel was released and contained on the well site. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update