

# Oil Field Environmental Incident Summary

**Incident:** 20190318123630      **Notice:** 3/18/2019    12:36      **Occurred:** 3/18/2019    06:39

**Responsible Party:** SCOUT ENERGY MANAGEMENT LLC

**Well Operator:** SCOUT ENERGY MANAGEMENT LLC

**Well Name:** DHSU Injection Plant

**Field Name:** DICKINSON

**Well File #:**

**Facility ID #:** 401646-03

**County:** STARK

**Twp Rng Sec Qtr:** 140   97   25   SE SE

**Location Description:**

**Submitted By:** Beki Sample

**Received By:**

**Contact Info:** Beki Sample  
4901 LBJ FREEWAY, STE 300  
DALLAS TX 75244

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 50 Feet

**Nearest Water Well:** 50 Feet

**Type of Incident:** Truck Overflow

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	2	Barrels	2	Barrels	2	barrels
<b>Brine</b>	2	Barrels	2	Barrels	0	barrels

**Other**

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:** 5/20/2019

**Written Report Recd:** 9/6/2019

**Risk Evaluation:**

N/A

**Areal Extent:**

N/A

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

A vac truck was dispatched to location and recovered the water and oil.

**Wastes Disposal Location:**

Water and oil will be returned to tanks. In the spring, soil will be tested and removed if necessary. Any contaminated soil will be taken to R360 Chimney Butte facility.

**Other Agencies Involved:**

## ***Updates***

---

***Date:*** 3/18/2019

***Status:*** Reviewed - Assigned to Other Agency

***No Further Action:*** ☒

***Author:*** O'Gorman, Brian

***Notes:***

Release, due to a truck overflow was contained to the well site, according to the report. NDIC retains oversight.

***Updated Volumes and Contaminant*** None at the time of this update