

# *Oil Field Environmental Incident Summary*

**Incident:** 20190320151904      **Notice:** 3/20/2019    15:19    **Occurred:** 3/20/2019    07:11

**Responsible Party:** EOG RESOURCES, INC.

**Well Operator:** EOG RESOURCES, INC.

**Well Name:** AUSTIN 424-1721H

**Field Name:** PARSHALL

**Well File #:** 34522

**Facility ID #:**

**County:** MOUNTRAIL

**Twp Rng Sec Qtr:** 154 90 17 NW NW

**Location Description:**

**Submitted By:** Brenda Vaness

**Received By:**

**Contact Info:**  
Brenda Vaness  
600 17TH ST., STE 1000N  
DENVER CO 80202

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:**

**Nearest Water Well:**

**Type of Incident:** Pump Leak

**Release Contained:** Yes - On Facility Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	30	Barrels	29	Barrels		

**Brine**

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:**

**Written Report Recd:**

**Risk Evaluation:**

N/A

**Areal Extent:**

**Potential Env. Impacts:**

N/A

**Action Taken/Planned:**

The jet pump was shut down to stop the leak. A vac truck vacuumed up pooled liquids, and a hydrovac truck removed additional liquids, contaminated snow/slush, and pad solids.

**Wastes Disposal Location:**

Liquids were pushed back into the production facility, and contaminated snow/slush, and pad solids to Secure, Stanley, ND.

**Other Agencies Involved:**

## **Updates**

---

**Date:** 3/20/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Schiermeister, Robin

**Notes:**

Release, due to a pump leak, remained on the well pad. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update