

Oil Field Environmental Incident Summary

Incident: 20190508122703 **Notice:** 5/8/2019 12:27 **Occurred:** 5/8/2019 09:30

Responsible Party: PETRO-HUNT, L.L.C.

Well Operator: PETRO-HUNT, L.L.C.

Well Name: SABROSKY 2-6-3B

Field Name: LITTLE KNIFE

Well File #: 9225

Facility ID #:

County: DUNN

Twp Rng Sec Qtr: 144 97 6

Location Description:

Submitted By: Shawn Reisenauer

Received By:

Contact Info: Shawn Reisenauer
390 119th Ave. SW
Killdeer ND 58640

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil					0	
Brine					0	
Other					0	

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 5/8/2019

Written Report Recd: 6/17/2019

Risk Evaluation:

none

Areal Extent:

75'x150' along northwest edge of pad

Potential Env. Impacts:

none

Action Taken/Planned:

Field personnel were able to extinguish fire.

Wastes Disposal Location:

NA

Other Agencies Involved:

Local Fire Department

Updates

Date: 5/8/2019 **Status:** Reviewed - Follow-up Required

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, there was a fire that made it off pad. Further follow-up is needed to ensure no oilfield contamination was released during fire.

Updated Volumes and Contaminant None at the time of this update

Date: 6/3/2019 **Status:** Inspection

No Further Action: ☒

Author: Schiermeister, Robin

Notes:

Arrived on site at 13:00 on 5-29-2019. It was sunny with temperatures in the 70s. The fire occurred northwest off the well pad. Walked over to the described area in the report and saw nothing but green grass with no signs of the contamination. During the inspection, it appears that the well pad and flare are not currently active. No further follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update