

# *Oil Field Environmental Incident Summary*

**Incident:** 20190514090104      **Notice:** 5/14/2019    09:01      **Occurred:** 5/13/2019    16:15

**Responsible Party:** Scout Energy Partners  
**Well Operator:** SCOUT ENERGY MANAGEMENT LLC  
**Well Name:** Heart River 1-4  
**Field Name:** STADIUM  
**Well File #:** 14212  
**Facility ID #:**  
**County:** STARK  
**Twp Rng Sec Qtr:** 139 96 5 SE NE  
**Location Description:**  
**Submitted By:** Beki Sample  
**Received By:**  
**Contact Info:** Beki Sample  
 4901 LBJ Freeway  
 Suite 300  
 Dallas TX 75244  
**Affected Medium:** Well/Facility Soil  
**General Land Use:** Well/Facility Site  
**Near. Occupied Bldg:** 70 Feet  
**Nearest Water Well:** 70 Feet  
**Type of Incident:** Other  
**Release Contained:** Yes - On Facility Site  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	40	Barrels	40	Barrels	40	barrels
<b>Brine</b>	20	Barrels	20	Barrels	20	barrels

**Other**

**Oth Rel. Contaminant:** N/A

**Date Inspected:**

**Clean Up Concluded:** 6/19/2019

**Written Report Recd:** 9/6/2019

**Risk Evaluation:**

None

**Areal Extent:**

N/A

**Potential Env. Impacts:**

There will be no environmental impacts

**Action Taken/Planned:**

Hydro vacs, Vac trucks, Hot Oil trucks and a roustabout crew were all dispatched to the scene for clean-up. Water was injected to kill the well until a rig and crew could be scheduled to replace surface casing

**Wastes Disposal Location:**

Solids will go to Indian Hills Disposal. Recovered oil will go back into storage tanks.

**Other Agencies Involved:**

**Updates**

---

**Date:** 5/14/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** Stockdill, Scott

**Notes:**

According to the incident summary, this spill remained on location. NDIC retains oversight.

**Updated Volumes and Contaminant**    None at the time of this update