

Oil Field Environmental Incident Summary

Incident: 20190516064043 **Notice:** 5/16/2019 06:40 **Occurred:** 5/14/2019 12:30

Responsible Party: EOG RESOURCES, INC.

Well Operator: EOG RESOURCES, INC.

Well Name: AUSTIN 19-30H

Field Name: PARSHALL

Well File #: 17500

Facility ID #:

County: MOUNTRAIL

Twp Rng Sec Qtr: 154 90 30

Location Description:

Submitted By: Danielle Dupay

Received By:

Contact Info: Danielle Dupay
600 17TH ST., STE 1000N
DENVER CO 80202

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak

Release Contained: Yes - Within Dike

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	40	Barrels	40	Barrels		

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

Potential Env. Impacts:

None

Action Taken/Planned:

Hydrovac was used to removed contaminated material and liquids

Wastes Disposal Location:

Secure, Stanley ND

Other Agencies Involved:

Updates

Date: 5/16/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill remained on location. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update