

Oil Field Environmental Incident Summary

Incident: 20190516090913 **Notice:** 5/16/2019 09:09 **Occurred:** 5/14/2019 11:54

Responsible Party: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Operator: BURLINGTON RESOURCES OIL & GAS COMPANY LP

Well Name: MIDNIGHT RUN 11-1MBH

Field Name: UNION CENTER

Well File #: 20323

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 152 96 1

Location Description:

Submitted By: KELSY Waggaman

Received By:

Contact Info: Kelsy Waggaman
925 North Eldridge Pkwy
HOUSTON TX 77079

Affected Medium: Topsoil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other

Oth Rel. Contaminant: None

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None

Areal Extent:

30 X 60 feet off location on West side of pad.

Potential Env. Impacts:

Ash on topsoil.

Action Taken/Planned:

Fire was extinguished by hand, no fire extinguishers were used.

Wastes Disposal Location:

N/A

Other Agencies Involved:

Updates

Date: 5/16/2019 **Status:** Reviewed - Follow-up Required

No Further Action:

Author: Stockdill, Scott

Notes:

According to the incident summary, this spill impacted areas off of location. Follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update

Date: 5/23/2019 **Status:** Inspection

No Further Action:

Author: Crowdus, Kory

Notes:

On location 5/23/2019, at 10:41am. No remaining impacts seen at this time. No further follow-up is required.

Updated Volumes and Contaminant None at the time of this update