

Oil Field Environmental Incident Summary

Incident: 20190522141315 **Notice:** 5/22/2019 14:13 **Occurred:** 5/22/2019 02:30

Responsible Party: HUNT OIL COMPANY
Well Operator: HUNT OIL COMPANY
Well Name: HALLIDAY 146-93-13-1H- 1
Field Name: WOLF BAY
Well File #: 34912
Facility ID #:
County: DUNN
Twp Rng Sec Qtr: 146 93 13
Location Description: Well site.
Submitted By: David McWethy
Received By:
Contact Info: Daniel Delancey
 1900 N Akard St
 DALLAS TX 75201-2300

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Tank Overflow
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	100	Barrels	100	Barrels		

Oth Rel. Contaminant:
Date Inspected:
Clean Up Concluded:
Written Report Recd:
Risk Evaluation:

There are no immediate known hazards.

Areal Extent:

Potential Env. Impacts:

All fluids were sucked up and soil will be remediated when job is complete.

Action Taken/Planned:

Fluids sucked up and disposed of. Contaminated soil will be remediated when job is complete.

Wastes Disposal Location:

Approved waste disposal facility.

Other Agencies Involved:

Updates

Date: 5/22/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: Martin, Russell

Notes:

Release due to tank overflow remained on location, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update