

Oil Field Environmental Incident Summary

Incident: 20190630163720 **Notice:** 6/30/2019 16:37 **Occurred:** 6/29/2019 18:30

Responsible Party: A&D Trucking
Well Operator: SLAWSON EXPLORATION COMPANY, INC.
Well Name: OSPREY FEDERAL 1-26-25-30H
Field Name: BIG BEND
Well File #: 18749
Facility ID #:
County: MOUNTRAIL
Twp Rng Sec Qtr: 151 92 26 SE SW
Location Description: 175 yards south of the pad, 15' off of the road to the east.
Submitted By: Ray Gorka
Received By:
Contact Info: Aaron Bennet
 12 Emma Ln
 Ross ND 58776

Affected Medium: Topsoil
General Land Use: Cultivated
Near. Occupied Bldg: 11600 Feet
Nearest Water Well: 11600 Feet
Type of Incident: Vessel Leak
Release Contained: No
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	4	Barrels	4	Barrels		
Other						

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

none

Areal Extent:

about 10' X 12'

Potential Env. Impacts:

salty soil, removed, will be replaced with clean.

Action Taken/Planned:

Driver put on suspension, whole company notified to be more careful

Wastes Disposal Location:

Secure Energy Services

Other Agencies Involved:

Updates

Date: 7/1/2019

Status: Reviewed - Assigned to Other Agency

No Further Action:

Author: DeVries, Taylor

Notes:

According to the incident report, the release of 4 barrels of brine was not contained. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

Updated Volumes and Contaminant None at the time of this update