

Oil Field Environmental Incident Summary

Incident: 20190705095441 **Notice:** 7/5/2019 09:54 **Occurred:** 7/4/2019 10:30

Responsible Party: PETRO-HUNT, L.L.C.
Well Operator: PETRO-HUNT, L.L.C.
Well Name: USA 153-95-3A-10- 4H
Field Name: CHARLSON
Well File #: 34658
Facility ID #:

County: MCKENZIE
Twp Rng Sec Qtr: 154 95 34 SE SW

Location Description:
Submitted By: Derek Enderud
Received By:
Contact Info: Derek Enderud
 PO BOX 935
 BISMARCK ND 58502

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site

Near. Occupied Bldg:
Nearest Water Well:

Type of Incident: Valve/Piping Connection Leak
Release Contained: Yes - On Constructed Well Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine						
Other	50	Barrels	50	Barrels		

Oth Rel. Contaminant: Frac Gel

Date Inspected:
Clean Up Concluded:
Written Report Recd:

Risk Evaluation:
 Unstable walking surface

Areal Extent:
Potential Env. Impacts:
 Contaminated pad surface material

Action Taken/Planned:
 SLB cleaned up contaminates and hauled to disposal

Wastes Disposal Location:
 WISCO

Other Agencies Involved:
 USFS-McKenzie Ranger District

Updates

Date: 7/5/2019

Status: Reviewed - Assigned to Other Agency

No Further Action:

Author: DeVries, Taylor

Notes:

According to the incident report, the release of frac gel was contained to the well pad. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update