

# *Oil Field Environmental Incident Summary*

**Incident:** 20190705174034      **Notice:** 7/5/2019      17:40      **Occurred:** 7/5/2019      01:00

**Responsible Party:** HENRY HILL OIL SERVICES, LLC

**Well Operator:** HENRY HILL OIL SERVICES, LLC

**Well Name:** ND STATE 1-16 SWD

**Field Name:** CATWALK

**Well File #:** 7504

**Facility ID #:**

**County:** WILLIAMS

**Twp Rng Sec Qtr:** 154 100 16

**Location Description:**

**Submitted By:** Matt Azure

**Received By:**

**Contact Info:** Matt Azure  
120 26TH STREET EAST  
SUITE 200  
WILLISTON ND 58801

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 1 Mile

**Nearest Water Well:** 1 Mile

**Type of Incident:** Pump Leak

**Release Contained:** Yes - On Constructed Well Site

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	30	Barrels	30	Barrels	30	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 7/6/2019

**Written Report Recd:** 7/8/2019

**Risk Evaluation:**

soil on site

**Areal Extent:**

NA

**Potential Env. Impacts:**

soil on site

**Action Taken/Planned:**

water sucked up and soil removed taken to secure waste management.

**Wastes Disposal Location:**

water will be reinjected, and soil will be taken to secure waste site.

**Other Agencies Involved:**

NDIC Jessica

## **Updates**

---

**Date:** 7/8/2019      **Status:** Reviewed - Assigned to Other Agency      **No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release was contained on location. NDIC takes oversight.

**Updated Volumes and Contaminant**    None at the time of this update