

Oil Field Environmental Incident Summary

Incident: 20190708201311 **Notice:** 7/8/2019 20:13 **Occurred:** 7/7/2019 03:40

Responsible Party: Excel trucking
Well Operator: HENRY HILL OIL SERVICES, LLC
Well Name: Nelson SWD
Field Name: LONE TREE
Well File #: 90404
Facility ID #:
County: WILLIAMS
Twp Rng Sec Qtr: 157 99 9 NE SE
Location Description:
Submitted By: Matt Azure
Received By:
Contact Info: Keneth Miller
 4 2ed street west
 Williston ND 58801

Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 1 Mile
Nearest Water Well: 1 Mile
Type of Incident: Equipment Failure
Release Contained: Yes - On Facility Site
Reported to NRC: No

| | Spilled | Units | Recovered | Units | Followup | Units |
|--------------|---------|---------|-----------|---------|----------|---------|
| Oil | | | | | | |
| Brine | 20 | Barrels | 20 | Barrels | 20 | barrels |
| Other | | | | | | |

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded: 7/7/2019

Written Report Recd: 9/6/2019

Risk Evaluation:

soil on site

Areal Extent:

Potential Env. Impacts:

soil on site

Action Taken/Planned:

water was sucked up and soil removed. have drivers watching their truck , not sitting in cab.

Wastes Disposal Location:

water was re injected and soil was taken to solid waste facilitie

Other Agencies Involved:

NDIC

Updates

Date: 7/9/2019

Status: Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: DeVries, Taylor

Notes:

According to the incident report, the release stayed on location. NDIC takes oversight.

Updated Volumes and Contaminant None at the time of this update