

# *Oil Field Environmental Incident Summary*

**Incident:** 20190709112437      **Notice:** 7/9/2019      11:24      **Occurred:** 7/8/2019      1700

**Responsible Party:** Rogue Pressure Services  
**Well Operator:** SLAWSON EXPLORATION COMPANY, INC.  
**Well Name:** ZEPHYR 2-36H  
**Field Name:** BIG BEND  
**Well File #:** 20204  
**Facility ID #:**  
**County:** MOUNTRAIL  
**Twp Rng Sec Qtr:** 151 93 1 NW NW  
**Location Description:** Pad and 155' X 72' off site to Southeast of pad.  
**Submitted By:** Ray Gorka  
**Received By:**  
**Contact Info:** Jake Gadbois  
 8601 Derrick Ave.  
 Williston ND 58801

**Affected Medium:** Topsoil  
**General Land Use:** Cultivated  
**Near. Occupied Bldg:** 1300 Feet  
**Nearest Water Well:** 1300 Feet  
**Type of Incident:** Vessel Leak  
**Release Contained:** No  
**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>	3.3	Barrels	3.3	Barrels	3.3	barrels

**Brine**  
**Other**

**Oth Rel. Contaminant:** ....

**Date Inspected:**

**Clean Up Concluded:** 7/28/2019

**Written Report Recd:** 8/7/2019

**Risk Evaluation:**

none.

**Areal Extent:**

155' X 72'

**Potential Env. Impacts:**

none, crop has a mist of oil on it.

**Action Taken/Planned:**

wait for crop owner to decide if want cut and removed or leave and watch growth.

**Wastes Disposal Location:**

Secure Energy services will receive any waste.

**Other Agencies Involved:**

## Updates

---

**Date:** 7/9/2019

**Status:** Reviewed - Assigned to Other Agency

**No Further Action:**

**Author:** DeVries, Taylor

**Notes:**

According to the incident report, the release of crude oil was not contained to the well pad. Location is within MHA nation. Report forwarded to MHA environmental, BIA, and EPA.

**Updated Volumes and Contaminant** None at the time of this update