

Oil Field Environmental Incident Summary

Incident: 20190709132046 **Notice:** 7/9/2019 13:20 **Occurred:** 7/8/2019 0930

Responsible Party: Basic Energy Services
Well Operator: BASIC ENERGY SERVICES, L.P.
Well Name: Stanley SWD #3
Field Name:
Well File #: 90160
Facility ID #:
County: MOUNTRAIL
Twp Rng Sec Qtr: 158 91 27 NW NW
Location Description: Basic Energy Services, Stanley SWD #3, Commercial Salt water disposal
Submitted By: Mark Ehrlich
Received By:
Contact Info: Shane Dimando
801 Cherry Street
2100, Ut. 21
Fort Worth TX 76102
Affected Medium: Well/Facility Soil
General Land Use: Well/Facility Site
Near. Occupied Bldg: 30 Feet
Nearest Water Well: 1 Mile
Type of Incident: Fire
Release Contained: Yes - On Facility Site
Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	200	Barrels				
Brine	3500	Barrels				
Other						

Oth Rel. Contaminant: Vacuuming up fluids today, 7/9/19. Totals recovered, not yet known. Much of the crude oil in inventory likely burned.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

None, facility is shut down until repairs are made

Areal Extent:

Contained within firewall

Potential Env. Impacts:

Fluids were contained inside firewall. Immediate removal of fluids by vacuum truck was begun. Firewall area is lined, so potential impact to environment is likely minimal. Small affected area outside firewall on well site was excavated and is stored for later disposal.

Action Taken/Planned:

Spill was contained inside the firewall and fluids were being picked up and taken to disposal. Any affected soils will be properly remediated and or disposed.

Wastes Disposal Location:

Bakken Backwash #4, Basic Energy Services

Other Agencies Involved:

Local Fire Department, Local Law Enforcement, Division of Emergency Services

Updates

Date: 7/9/2019 **Status:** Reviewed - Follow-up Required **No Further Action:**

Author: DeVries, Taylor

Notes:

According to the incident report, the release was contained on site. Contact will be made to make sure all contaminants remained on location.

Updated Volumes and Contaminant None at the time of this update

Date: 7/9/2019 **Status:** Inspection **No Further Action:**

Author: Stockdill, Scott

Notes:

Arrived on location 7:05 7/9/2019.

No sign of release leaving dike. Vac truck on location sucking out water in dike that has mixed with rainwater.

No follow-up is necessary.

Updated Volumes and Contaminant None at the time of this update