

Oil Field Environmental Incident Summary

Incident: 20190713100716 **Notice:** 7/13/2019 10:07 **Occurred:** 7/12/2019 19:10

Responsible Party: WPX ENERGY WILLISTON, LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: HONEY LOCUST 18-19HIL

Field Name: SQUAW CREEK

Well File #: 35446

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 149 94 18

Location Description:

Submitted By: Teresa Van Deusen

Received By:

Contact Info: Teresa Van Deusen
3500 One Williams Center- MD38
TULSA OK 74172

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Fire

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	2	Gallons	2	Gallons		

Brine

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

No immediate risk.

Areal Extent:

Potential Env. Impacts:

No impacts.

Action Taken/Planned:

Fire self-extinguished within the flare pit. Scorched scoria, all grass behind flares to is being mowed/bagged for disposal. Regulator for oil dump is being replaced today. No further actions to be taken.

Wastes Disposal Location:

Well/facility soil and grass will be disposed of at a permitted E&P exempt solid waste landfill

Other Agencies Involved:

Updates

Date: 7/17/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

Released located within MHA Nation. Report forwarded to BIA, EPA and MHA Environmental.

Updated Volumes and Contaminant None at the time of this update