

Oil Field Environmental Incident Summary

Incident: 20190715152001 **Notice:** 7/15/2019 15:20 **Occurred:** 7/15/2019 12:45

Responsible Party: WHITE ROCK OIL & GAS LLC

Well Operator: WHITE ROCK OIL & GAS, LLC

Well Name: ERRMU 1-18

Field Name: ROUGH RIDER

Well File #: 7224

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 145 100 18 NW SW

Location Description:

Submitted By: ERIC LINTHICUM

Received By:

Contact Info: ERIC LINTHICUM
5810 TENNYSON PKWY
SUITE 500
PLANO TX 75024

Affected Medium: Well/Facility Soil

General Land Use: Well/Facility Site

Near. Occupied Bldg:

Nearest Water Well:

Type of Incident: Equipment Failure

Release Contained: Yes - On Constructed Well Site

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
Oil	0.5	Barrels				
Brine	0.5	Barrels				

Other

Oth Rel. Contaminant:

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

No risk at this time

Areal Extent:

Potential Env. Impacts:

Soil on the site.

Action Taken/Planned:

Casing valve to be repaired and soil will be cleaned.

Wastes Disposal Location:

Other Agencies Involved:

Updates

Date: 7/17/2019 **Status:** Reviewed - Assigned to Other Agency

No Further Action: ☒

Author: O'Gorman, Brian

Notes:

Release, due to equipment failure was contained to the well site, according to the report. NDIC retains oversight.

Updated Volumes and Contaminant None at the time of this update