

# *Oil Field Environmental Incident Summary*

**Incident:** 20190809104914      **Notice:** 8/9/2019      10:49      **Occurred:** 8/9/2019      09:15

**Responsible Party:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Operator:** PETRO HARVESTER OPERATING COMPANY, LLC

**Well Name:** JENSEN 3

**Field Name:** FLAXTON

**Well File #:** 9695

**Facility ID #:**

**County:** BURKE

**Twp Rng Sec Qtr:** 163 90 7 SW NW

**Location Description:**

**Submitted By:** Bill Bender

**Received By:**

**Contact Info:** Bill Bender  
5005 LYNDON B JOHNSON FREEWAY  
SUITE 700  
DALLAS TX 75244

**Affected Medium:** Well/Facility Soil

**General Land Use:** Well/Facility Site

**Near. Occupied Bldg:** 5045 Feet

**Nearest Water Well:** 5045 Feet

**Type of Incident:** Equipment Failure

**Release Contained:** Yes - Within Dike

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	15	Barrels	15	Barrels	15	barrels

**Other**

**Oth Rel. Contaminant:**

**Date Inspected:**

**Clean Up Concluded:** 8/27/2019

**Written Report Recd:** 9/9/2019

**Risk Evaluation:**

No immediate explosive atmosphere or health hazard risk.

**Areal Extent:**

**Potential Env. Impacts:**

No impact to surface water or ground water.

**Action Taken/Planned:**

A vacuum truck recovered the released fluid inside containment, and recycled the fluid on location. Affected soils inside containment will be scraped-up, collected and hauled to an approved disposal facility. The injection line will be repaired on 8/9/19.

**Wastes Disposal Location:**

At an approved disposal facility.

**Other Agencies Involved:**

## Updates

---

**Date:** 8/9/2019

**Status:** Reviewed - Assigned to Other Agency

**No Further Action:**

**Author:** Martin, Russell

**Notes:**

Release due to equipment failure remained on location, according to the report. NDIC retains oversight.

**Updated Volumes and Contaminant** None at the time of this update