

Oil Field Environmental Incident Summary

Incident: 20190811095450 **Notice:** 8/11/2019 09:54 **Occurred:** 8/10/2019 21:00

Responsible Party: BTJ Energy Services LLC

Well Operator: WPX ENERGY WILLISTON, LLC

Well Name: BEAVER 22-21HX

Field Name: SQUAW CREEK

Well File #: 35908

Facility ID #:

County: MCKENZIE

Twp Rng Sec Qtr: 149 94 27 NE NW

Location Description: Incident occurred on lease road to the WPX Energy Beaver 22-21H Facility, at GPS coordinates 47.701275°, -102.694716°

Submitted By: Adam Ries

Received By:

Contact Info: Adam Ries
PO Box 657
Parshall ND 58770

Affected Medium: Topsoil

General Land Use: Pasture

Near. Occupied Bldg: 1 Mile

Nearest Water Well: 0.3 Mile

Type of Incident: Other

Release Contained: No

Reported to NRC: No

	Spilled	Units	Recovered	Units	Followup	Units
--	----------------	--------------	------------------	--------------	-----------------	--------------

Oil

Brine

Other	27	Barrels	27	Barrels		
--------------	----	---------	----	---------	--	--

Oth Rel. Contaminant: Approximately 27 tons of drill cuttings (used with oil-based drilling mud) were released.

Date Inspected:

Clean Up Concluded:

Written Report Recd:

Risk Evaluation:

No immediate risks associated with this incident. Temporary fence will be install to prevent livestock access.

Areal Extent:

Approximately 5,100 square feet of land surface (lease road and ditch).

Potential Env. Impacts:

Release impacted the lease road and soil in the roadside ditch. Material was immediately recovered and erosion BMP's were installed.

Action Taken/Planned:

Drill cuttings were recovered with a skid-steer loader. Soil testing, excavation, and reclamation activities will be conducted as necessary.

Wastes Disposal Location:

Permitted, E&P exempt landfill or full-service terminal.

Other Agencies Involved:

MHA Energy/TAT Environmental/BIA/BLM/ Local Law Enforcement

Updates

Date: 8/12/2019 **Status:** Reviewed - Assigned to Other Agency **No Further Action:**

Author: O'Gorman, Brian

Notes:

According to the report, 27 barrels of drill cuttings were released and not contained. Location is within MHA nation. Report forwarded to MHA Environmental, BIA and EPA.

Updated Volumes and Contaminant None at the time of this update