Oil Field Environmental Incident Summary

Incident: 2010	0051524		100,0/E/2010	15.01	20011	od. 0/4/2010	12:17
Incident: 201909051531 Responsible Party:			otice: 9/5/2019			ed: 9/4/2019	12.17
-	arty:	BURLINGTON RESOURCES OIL & GAS COMPANY LP BURLINGTON RESOURCES OIL & GAS COMPANY LP					
Well Operator: Well Name:		CRATERHAWK 8-14 UTFH-ULW					
Field Name:		ANTELOPE					
Well File #:		31623					
Facility ID #:		51025					
County:		MCKENZIE					
Twp Rng Sec Qtr:		152 95 14					
Location Desci		102 00					
Submitted By:		Kelsy Waggaman					
Received By:							
Contact Info:	-						
		925 North Eldridge Pkwy					
		HOUSTON	TX 77079				
Affected Mediu	ım:	Topsoil					
General Land L	Jse:	Well/Facility	Site				
Near. Occupied Bldg:							
Nearest Water	Well:						
Type of Incider	nt:	Other					
Release Conta	ined:	No					
Reported to NF	RC:	No					
•							
S	billed	Units	Recovered	Units		Followup	Units
Oil	billed 35	<i>Units</i> Gallons	Recovered	Units		Followup 35	<i>Units</i> gallons
Oil Brine			Recovered	Units	1		
Oil Brine Other	35	Gallons	Recovered	Units	1		
Oil Brine Other Oth Rel. Conta	35 minant:	Gallons	Recovered	Units	I		
Oil Brine Other Oth Rel. Conta Date Inspected	35 <i>minant:</i> I:	Gallons N/A	Recovered	Units	1		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc	35 minant: I: :luded:	Gallons N/A 9/9/2019	Recovered	Units	1		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report	35 minant: I: :luded: Recd:	Gallons N/A	Recovered	Units	I		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation	35 minant: I: :luded: Recd:	Gallons N/A 9/9/2019	Recovered	Units	I		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None	35 minant: I: :luded: Recd:	Gallons N/A 9/9/2019	Recovered	Units	1		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent:	35 minant: I: Sluded: Recd: n:	Gallons N/A 9/9/2019 2/28/2020		Units	I		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent: 120' x 600' fine,	35 minant: I: :: Iuded: Recd: n: intermitte	Gallons N/A 9/9/2019 2/28/2020		Units			
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent:	35 minant: I: Eluded: Recd: n: intermitte	Gallons N/A 9/9/2019 2/28/2020		Units	1		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent: 120' x 600' fine, Potential Env.	35 minant: I: :: luded: Recd: n: intermitte Impacts: tion.	Gallons N/A 9/9/2019 2/28/2020		Units			
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent: 120' x 600' fine, Potential Env. Oil mist off locat Action Taken/F	35 minant: I: :: uded: Recd: n: intermitte Impacts: tion. Planned:	Gallons N/A 9/9/2019 2/28/2020			cked.		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent: 120' x 600' fine, Potential Env. Oil mist off locat Action Taken/F	35 minant: I: :: : : : : : : : : : : : : : : : :	Gallons N/A 9/9/2019 2/28/2020 ent aerosol m	ist		cked.		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Conc Written Report Risk Evaluation None Areal Extent: 120' x 600' fine, Potential Env. I Oil mist off locat Action Taken/F	35 minant: I: :: : : : : : : : : : : : : : : : :	Gallons N/A 9/9/2019 2/28/2020 ent aerosol m	ist		cked.		
Oil Brine Other Oth Rel. Conta Date Inspected Clean Up Cond Written Report Risk Evaluation None Areal Extent: 120' x 600' fine, Potential Env. Oil mist off locat Action Taken/F Well instrumenta	35 minant: I: cluded: Recd: n: intermitte Impacts: tion. Planned: ation and cal Locat	Gallons N/A 9/9/2019 2/28/2020 ent aerosol m	ist		cked.		

Updates

Date:
9/6/2019
Status:
Reviewed - Follow-up Required
No Further Action:
✓

Author:
O'Gorman, Brian
Notes:
According to the report, 35 gallons of oil was released and not contained. Further follow-up needed.
Updated Volumes and Contaminant
None at the time of this update

Date:
9/11/2019
Status:
Inspection - More Follow-up Required
No Further Action:
✓

Author:
O'Gorman, Brian
Notes:
No Further Action:
✓

Author:
O'Gorman, Brian
Notes:
No Further Action:
✓

Arrived at the location with a Burlington representative at 12:00. The representative showed me the
More status (Inspection (Ins

area that had been impacted and stated that it was released from the flare on the east side of the pad. It appeared that the release was contained to a new pipeline right-of-way (ROW) north of the minimum maintenance road. General GPS coordinates: 47.992193, -102.791942. The ROW had been stripped of its topsoil and had the piping still above ground. Did not notice any stained soils or impacted subsoils. A vegetation check should be completed next growing season to check for proper plant growth in the area. Photos added to the incident folder.

Updated Volumes and Contaminant None at the time of this update

Date: 5/4/2020 Status: Inspection - No Action Required

No Further Action: 🗸

Author: Crowdus, Kory

Notes:

On location 5/4/2020, at 3:44pm. No remaining impacts seen at this time. No further follow-up is required.

Updated Volumes and Contaminant None at the time of this update